



Assess Hautwood Avenue Hayward, CA 94544 Tel: 888.968.1668 Fax: 510.475.0982 www.posiflexusa.com

Memo

To: POSIFLEX Customers

From: POSIFLEX Operations Department

Date: 4/2/2014

Re: End of Repair Notice: TP8015/ TP8415 Series

Dear POSIFLEX Customer:

Posiflex announces End of Repair services for the TP8015 and TP8415 models due to no longer having sufficient parts available to maintain a complete repair program for the TP8015/8415 models.

The TP8015/8415 models were discontinued March 2010 and are no longer eligible for the post warranty repair program.

The following models are affected by this notice:

JIVA TP8015 Series Touch Terminals JIVA TP8415 Series Touch Terminals

Limited parts are available for self-service; please contact Customer Service Department for specific availability.

Email: <u>Customer.Service@Posiflexusa.com</u>

Tel: (510) 429-7097

Please note that the current model, TP8315 is <u>not</u> affected by this notice. Warranty and Post Warranty services remain available for this model only.

Posiflex greatly appreciates your support.

Regards,

Posiflex Business Machines